

- 1. SERVICE LAYOUT ON RIGHT LOT IS A MIRROR TO ABOVE
- 2. 4 PARTY TRENCH SHOULD NOT BE USED BEHIND PADMOUNTED TRANSFORMER DUE TO CONFLICT WITH GAS
- 3. THE POSITION OF ALL POLE LINES, CONDUITS, WATER MAINS SEWERS, AND OTHER UNDERGROUND AND ABOVE GROUND UTILITIES AND STRUCTURES ARE NOT NECESSARILY AS SHOWN. THE ACCURACY OF THE POSITION OF SUCH UTILITIES AND STRUCTURES IS NOT GUARANTEED. BEFORE STARTING WORK, DETERMINE THE EXACT LOCATION OF ALL SUCH UTILITIES AND STRUCTURES AND ASSUME ALL LIABILITY FOR DAMAGE TO THEM.

Revisions 1. Sept 7, 2023 General rev of trench cross section

